


Plumpton Parish Council

Inspection Report

This report shows Findings and Tasks recorded during the Inspection(s) matching the selection criteria set in the Report Wizard. If no Findings or Tasks are shown, none were recorded.

Each Inspection includes a declaration signed by the Inspector stating that no defects were found other than those recorded.

Inspections included in this report


Provider	Lewes District Council	 26/06/2024
Site Name	Plumpton play area	
Actual Date	26/06/2024 08:29:38	
Inspection Type	Playground-Routine Visual	
Inspector	Nicky Soltermann	
Inspection Status	Completed	

Finding Summary

Plumpton play area Findings

Asset	Finding Title	Creation Date	Resolve By Date	Risk Level
Frame & Net	Item - Cap missing	25/01/2024 12:13:28		Low
Frame & Net	Item - Cap missing	29/04/2024 09:43:42		Low
Frame & Net	Delamination of Wood	28/05/2024 12:21:10		Low
Flat Seat Surface	Surface - Encroaching vegetation/trees	26/06/2024 08:36:58		Low
- Surface	Surface - Grass, Moss or Weeds	26/06/2024 08:40:06		Low

Inspection - Plumpton play area - 26/06/2024 08:29:38

Provider	Lewes District Council	
Site Name	Plumpton play area	
Actual Date	26/06/2024 08:29:38	
Inspection Type	Playground-Routine Visual	
Inspector	Nicky Soltermann	
Inspection Status	Completed	

Site Name	Plumpton play area
Address	
Postcode	
Notes	

Findings reported within the Inspection

- Surface - Finding

Asset	- Surface
Finding Title	Surface - Grass, Moss or Weeds
Finding Group	Maintenance
Cause	
Finding Status	Open
Finding Creation Date	26/06/2024 08:40:06
Resolve By Date	
Finding Resolved Date	
Risk Level	Low
Finding Notes	Remove weeds/grass coming through surface

Finding Photos



Flat Seat Surface - Finding

Asset	Flat Seat Surface
Finding Title	Surface - Encroaching vegetation/trees
Finding Group	Maintenance
Cause	Routine
Finding Status	Open
Finding Creation Date	26/06/2024 08:36:58
Resolve By Date	
Finding Resolved Date	
Risk Level	Low
Finding Notes	Weeds coming through surface

Finding Photos



Previously Reported Findings (unresolved at time of Inspection)

Frame & Net - Findings

Asset	Frame & Net
Finding Title	Delamination of Wood
Finding Group	Maintenance
Cause	Wear and Tear
Finding Status	Open
Finding Creation Date	28/05/2024 12:21:10
Resolve By Date	
Finding Resolved Date	
Risk Level	Low
Finding Notes	Monitor - starting to rot

Finding Photos



Asset	Frame & Net
Finding Title	Item - Cap missing
Finding Group	Maintenance
Cause	
Finding Status	Open
Finding Creation Date	29/04/2024 09:43:42
Resolve By Date	
Finding Resolved Date	
Risk Level	Low
Finding Notes	Cap missing

Finding Photos



Asset	Frame & Net
Finding Title	Item - Cap missing
Finding Group	Maintenance
Cause	Wear and Tear
Finding Status	Open
Finding Creation Date	25/01/2024 12:13:28
Resolve By Date	
Finding Resolved Date	
Risk Level	Low
Finding Notes	Cap missing